APPENDIX D 2022 Stormwater Master Plan Project Rankings

		F	Ranking Criteri	a				
Work Orders	Safety (40)	Capacity (15)	Maint. (30)	Pipe type (10)	Multi. Project Work (5)	Total Rank	Address	Comments
14484	40	15	30	10	5	100	Harvest Ln. 2200west down through Camelot and Richland Estates	ADS, Corrugated pipe and easement Lines. Flooding areas.
12578	40	5	30	10	5	90	8245 south / Lynn Ln	Easement line, Corrugated pipe and valley gutter. Flooding Area.
18435	40	5	30	10	5	90	Dixie Park to 3200west North City Boundaries	Corrugated pipe, easement line and Combination system.
18336	40	15	20	10	5	90	Bora Bora 1350west	Easement Lines. Combination system and Corrugated Pipe.
18396	40	15	20	10	5	90	7500south 2700west	Corrugated pipe, combination system and easement lines.
18408	40	10	30	0	5	85	Bagley Park and Dannon Way.	This helps the water department as well Road flooding.
23100	40	15	20	10	0	85	8100south U-111	Corrugated pipe under U-111
18892	40	15	20	0	5	80	7783south 4950west	
18338	40	15	10	10	5	80	7200south 1300west	Corrugated pipe roots and easement line.
18409	40	5	30	0	5	80	Dannon Way 6165west	This helps the water department as well

		F	Ranking Criteri	a				
Work Orders	Safety (40)	Capacity (15)	Maint. (30)	Pipe type (10)	Multi. Project Work (5)	Total Rank	Address	Comments
								Street overlay of
16941	30	15	15	10	5	75	6200south 4520west	ł
								Separate
								Combination
47200	20	10	20		_	75	0000	system and
17288	30	10	30	0	5	75	9000south 1075west	easement line.
							Barneys Creek	
							between 4800west	Culvert under
23020	40	15	20	0	0	75	and 4500west	roads
								City has
								identified that
								ADS pipe
								crossing
								Redwood Road
								are damaged and
							Drake Lane Redwood	
23056	40	5	20	5	5	75	Road	replaced. City has
							7600south Redwood	1 '
23057	40	5	20	5	5	75	Road	ADS pipe
23037			20			,,,	Rodd	ADS PIPE
								Easement line,
								Corrugated Pipe
18667	30	5	20	10	5	70	8565south 2931west	
								Corrugated Line
							Westborough Way	and easement
18325	30	10	20	5	5	70	6950south	line.
								Easement lines
							Bueno Vista Drive	Corrugated pipe
							2200west to	and combination
18311	30	5	20	10	5	70	1300west	system.
		J						
								Easement Line
								also. Installed a
								few inlets on the
								north side of the
								road we will
								need to access if
							Valley West Dr	we need to do
18833	40	5	20	0	5	70	3645west	more.

		F	Ranking Criteri	a				
Work Orders	Safety (40)	Capacity (15)	Maint. (30)	Pipe type (10)	Multi. Project Work (5)	Total Rank	Address	Comments
								Flows from
								Taylorsville.
								Open ditch right
22373	30	15	20	0	5	70	6645south 2200west	
								Easement lines
10057	20	10	10	10	_	65	6337South Dixie	and corrugated
18657	30	10	10	10	5	65	Drive	pipe.
18674	30	5	20	5	5	65	Alice Susanna Lane 6785south	ADS and easement lines. Floods in the parking lot behind strip mall.
10074	30		20				070530411	under sized
18309	30	5	30		0	65	7935south 2200west	pipes and road
10309	30	3	30		0	03	795350utii 2200West	Combination
								system and road
18626	30	5	30	0	0	65	Airport Road	flooding.
10020	30	,	30	0			Airport Road	Bubble up inlet.
23058	40	5	20	0	0	65	Sunrise Place 1655west	The inlet isn't tied into the system.
18735	30	5	10	10	5	60	6200south to 7000south 5600west to 4800west	Easement line also
								Easement line,
18661	30	15	10	10	5	60	Paddington Road Millerberg Way	corrugated pipe and Basin work.
18001	30	15	10	10	3	60	Willierberg way	Easement line
							Tanya Ave	and corrugated
18610	30	5	10	10	5	60	9246south	pipe.
10010	30	, ,	10	10	, ,	00	8970 South 2070	Easement lines
18416	30	5	20	5	5	60	West	and ADS pipe.
								Corrugated Line
							Sunrise Place	and easement
18346	30	5	10	10	5	60	7669south	line.
								Corrugated Line
							Skyvue Circle	and easement
18666	30	5	10	10	5	60	8223south	line.
								Easement lines,
							7000south	ADS and Valley
19027	30	10	10	5	5	60	Adventure Way	Inlets

		F	Ranking Criteria	a				
					NAME: Design			
l	o 6 : (40)			5: . (40)	Multi. Project			
Work Orders	Safety (40)	Capacity (15)	Maint. (30)	Pipe type (10)	Work (5)	Total Rank	Address	Comments
10000	20	_	20		_	60	O and such Chardeness	Valley Inlets and
19028	30	5	20	0	5	60	Oquirrh Shadows	Easement lines
							Aire and Daniel and	Valley Gutter
10020	20	45	10		_	60	Airport Road and	and Easement
19029	30	15	10	0	5	60	Center Park Drive	line.
								Facamant Lines
							7600south 2200west	Easement Lines
14478	30	10	10	5	5	60	to 1530west	
14476	30	10	10	3	3	00	to 1330Mest	system.
								Easement Line
							Beverly Glen Avenue	and combination
18393	30	15	10	?	5	60	2700west	system.
10000							2,000.030	System
								Bubble up is an
								easement line
23059	30	5	20	0	5	60	8948south 1240west	
								Valley Gutter
							Normandy Mobile	and Easement
18800	30	5	10	5	5	55	Home	line.
								System is a
18636	40	5	10	0	0	55	8900south 3020west	french drain.
								Basin isn't tied
							8660south 1841west	into the storm
23060	40	5	10	0	0	55	Gardner Lane	drain system.
								Easement line
								and corrugated
22532	0	15	20	10	5	50	7800south 1127West	pipe.
		_			_			Valley Inlets and
18348	30	5	10	0	5	50	7455south 1965west	
								This is the line
								leaving Skyview
40055	20	_	10		_	50	C550	Basin. Easement
18655	30	5	10	0	5	50	6550south 4000west	line.
								Valley gutter and
18660	30	_	10	0	_	50	6810south 3420west	
10000	30	5	10	J 0	5	30	001030utii 3420WeSt	casement iiie.
								Separate
								Combination
								System and
							Old Bingham	Valley gutter and
18669	30	5	10	0	5	50	-	easement lines.
				<u> </u>		1 55	10	-200

		Ranking Criteria						
					Multi. Project			
Work Orders	Safety (40)	Capacity (15)	Maint. (30)	Pipe type (10)		Total Rank	Address	Comments
								Combination
							7901south 3200west	system and
18670	30	5	10	0	5	50	Post Office	easement line
								flows to private
18707	30	5	10	0	5	50	8173south 3200west	property
								Valley Inlets and
10020	20	_	20		_	Γ0	7825south 3620west	Valley Inlets and
19030	30	5	20	0	5	50	782550uth 3620west	easement line.
							7560south Uranium	Valley Inlets and
18565	30	5	10	0	5	50	Drive	easement line.
10303	30				,	30	Dive	casement inter
								Easement Lines
							7400south 2200west	
14483	30	5	10	0	5	50	to 1300west	system.
								Easements and
								combination
18723	30	5	10	0	5	50	7878south 1410west	system.
							Wimbledon Ridge	
							Lane and Athleen	Easement line
18327	30	5	10	5	5	45	Drive	and ADS pipe.
18724	30	5	10	0	0	45	8660south 1500west	
					_		7854south Golden	irrigatin water in
18563	30	5	10	0	0	45	Pointe Way	gutter
								Basin and
10524		45	10	10	_	40	livelel Lana 04.40 accepts	corrugated and
18531	0	15	10	10	5	40	Judd Lane 9140south	
								Basin,
								corrugated pipe and Easement
18609	0	15	10	10	5	40	9000south 2585west	
18009	0	13	10	10	3	40	300030utii 2383West	Okubos basin
								and corrugated
18402	0	15	10	10	5	40	9000south 1850west	_
							Targhee Dr Laurel	Culvert for
18567	0	15	10	10	5	40	Ridge Drive	Drainage.
								This is the line
								leaving Plum
								Creek Wetland
18351	0	5	20	10	5	40	8380south 1300west	and ADS pipe.
								Easement line
								through
18401	0	15	10	10	5	40	8737south 1220west	Riverside

		Ranking Criteria						
	- (. ()				Multi. Project			
Work Orders	Safety (40)	Capacity (15)	Maint. (30)	Pipe type (10)	Work (5)	Total Rank	Address	Comments
								Combination
		_		_	_		Barton Hollow Drive	system and ADS
18347	0	5	10	5	5	35	1312 West	pipe.
							Toni Lee St.	ADC and Dasin
10507	0	-	10	10	_	20	2526west Browns Meadow South Basin	ADS and Basin
18587	0	5	10	10	5	30	IVIEAUOW SOULII BASIII	Basin,
							6775south Olympic	corrugated pipe
							Pointe Basin to	and easement
18553	0	5	10	10	5	30	3420west	line.
10000		3	10	10	3	30	3420We3t	inie.
								Easement line,
								corrugated pipe
								and Separate
								Combination
18555	0	5	10	10	5	30	8040south 1460west	
		_	_					Easement line
							Susan Way	and corrugated
18614	0	5	10	10	5	30	8641south	pipe.
								Easement line
								and corrugated
18554	0	5	10	10	5	30	7420south 3100west	pipe.
							Bueno Vista Drive	ADS pipe and
14720	0	5	10	5	5	30	2598 West	easement line.
								ADS, easement
								line and
							8430south Plum	combination
18410	0	5	10	5	5	25	Creek Drive	system.
								ADS, easement
								line and Valley
18890	0	5	10	5	5	25	1520west	Gutter.
								ADS, easement
								line and Separate
4000:	•	_	40	_		35	0220	Combination
18891	0	5	10	5	5	25	8230south 1336west	System.
10005	•	45	40			25	Bueno Vista Drive	
18895	0	15	10	0	0	25	2505west	easement line.
								Easement Lines
							7800south 2700west	
14722	0	5	10	5	5	25		system.
14122	U	5	10	J	5	23	Inviarious Flace	Easements and
								combination
20941	0	5	10	5	5	25	Derby Way 3200west	
20341	<u>_</u>	<u> </u>					120000000	13,300

		F	Ranking Criteri	a				
Work Orders	Safety (40)	Capacity (15)	Maint. (30)	Pipe type (10)	Multi. Project Work (5)	Total Rank	Address	Comments
Work Orders				pc type (=0)	, ,	Total Name	71001000	Combination
							Charing Cross	system and
18718	0	5	10	0	5	20	3384west	easement line.
								Easement Lines
							Callie Drive Duffys	and corrugated
14485	0	5	10	0	5	20	Lane	pipe.
								Easements and
								combination
18394	0	5	10	0	5	20	7268south 2700west	
								Easements and
,,,,,		_	4.0		_			combination
18411	0	5	10	0	5	20	8609south 1500west	system.
								Flows through private property, combination system and
18706	0	5	10	0	5	20	7185south 2700west	easement line.
18562	0	5	10	0	5	20	7945south Goldenpointe Way	Easement Line and combination system.
22377	0	5	10	0	5	20	6620south 2868west	Easement lines and valley inlets.
18412	0	5	10	0	0	15	Twin Oaks Drive 1308west	Line is cracked down the top of the pipe, too shallow.
18556	0	5	10	0	0	15	7503 S 2700 W	Tied to irrigation separate.
18887	?	?	?	?	?	?	City Wide	ADS and Corrugated also

	2022 Stormwater Master Plan Pipes and Culverts Project Rankings									
		F	Ranking Criteri	a						
	Multi. Proje									
Work Orders	Safety (40)	Capacity (15)	Maint. (30)	Pipe type (10)	Work (5)	Total Rank	Address	Comments		

	40 points - Property Damage or major storm drain system damage/ Possible for loss of life
Safety Definition	30 points -Street Flooding
	15 points - Pipe over 15 cfs
Canacity Definition	10 points - Pipe over 10 cfs up to 24"
Capacity Definition	5 points - pipe ofver 5 cfs up to 18"
	30 points - Repair and or maintenance is required in the next budget year
	20 points - Repair and or maintenance is required in the next 5 years
Maintenance Definition	
	10 points - Repair and or maintenance is required in the next 10 or more years
Pipe Type	10 points corrugated
Ріре Туре	5 points ADS
Multi Project	5 points - two or more areas

	2	2022 Storm	nwater Ma	ster Pla	n Stormwater Basin Project Rank	ings
Work		Ranking Criteria	3	Total		
Orders	Safety (50)	Impact (10)	Maint. (40)	Rank	Address	Comments
20072	50	10	40	100	Plum Creek 8380south Stratford Lane	This is a wetland. High banks. Heavy maintenance.
18313	40	10	40	90	6400south 4800west - Cougar Basin	Other city's water comes through our system and Corrugated pipe north side of basin and easement line.
22349	40	10	40	90	7000south 3200west - Constitution Park	We still need to get a design for the outlet structure.
22388	50	0	40	90	Bingham View Drive 4494west Dorilee/Festival Park	Flooding area in the past. Basin needs to be dug deeper.
17591	40	0	40	80	Discovery Drive 5825west - Discovery Basin	Basin is dangerous to maintain with a Vactor truck. Inlet box cracks and box grate bends under to much pressure.
18719	50	0	20	70	7413south Harvest Ridge Drive - Jordan Meadows Basin	Combination system, valley gutter and basin work
22350	40	0	20	60	9000south 1850west - Okubos Basin	see WO# 18402 Basin outlet structure holds water
19025	25	0	20	45	4400west Barrington Drive - Courtney Meadows	Basin is dangerous to maintain with a Vactor truck. Inlet box cracks and box grate bends under to much pressure.
19026	25	0	20	45	8951south Barney Wash Trail - Copperfield Basin	Easement line to basin. We need to move access gate to
18639 19591	25	0	10	35 0	8075south 5025west - Stone Hollow 1 City wide	Basin has a grade problem.

	50 points - Possible for loss of life and or Private property damage					
Safety Defintion (Flood Event)	40 points - Damage to stormwater assets inside the basin					
Safety Definition (Flood Event)	25 points - Damage to city vehicles working in the basin					
	10 points - Rainstorms removing Stormwater grates and or manhole lids					
Impacted by other cities or separate	10 points - Other cities flow flows through the basin or flows from irrigation and					
systems	or sub drain systems					
	40 points - Repair and or maintenance is required several times a year					
Maintenance Defintion	20 points - Repair and or maintenance is required once a year					
	10 points - Repair and or maintenance is required every few years					

	2022 Stormwater Master Plan Drainage Work Project Rankings										
		Ranking Criteria	1	Total							
Work Orders	Safety (60)	Impacted (10)	Maint. (20)	Rank	Address	Comments					
						Carries water					
						from South					
14663	60	10	10	80	Bingham Creek 8160south 1876west	Jordan City					
						Carries water					
					Bingham Creek from 4000west to Vista West	from South					
2654	40	10	20	70	Park	Jordan City					
						How are we					
						going to					
						address the					
						Unmanicured					
19624				0	City Wide	basin.					

Safety = Defintion 60 points - Possible for loss of life and or Private property damage 40 points - Damage to stormwater assets inside channel

40 points - Repairs and or maintenance is required yearly

Maintenance Defintion

20 points - Repairs and or maintenance is required once every few years 10 points - Repairs and or maintenance is required every five years